



Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservdelar / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Pieśe de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



XX = AA, AD...

**Position**

- 1 = A 960 333 XX
- 2 = A 960 590 XX
- 3 = A 962 594 NU
- 4 = A 961 820 XX
- 5 = A 960 800 XX
- 6 = A 960 529 XX
- 7 = A 960 492 NU
- 8 = A 962 335 NU
- 9 = A 963 004 NU
- 10 = A 960 512 NU
- 11 = A 961 819 NU
- 12 = A 960 556 NU
- 13 = A 960 516 NU
- 14 = A 960 517 NU
- 15 = A 960 520 NU
- 16 = A 963 033 NU





**MOMENTS**  
A 3920 ..





0811 / A 865 585  
 (+ A 865 612)  
 Made in Germany



Ideal Standard International BVBA  
 Chaussée de Wavre, 1789 - box 15  
 1160 Bruxelles  
 Belgium

www.idealstandardinternational.com





	<b>P</b> bar		MAX. 10		5		<b>Q</b> (3 bar)
	<b>T</b> °C		MAX. 80		65		<b>l/min</b>
					40		<b>20,5</b>

