





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

xx = AA,AD,..


**Position**

- 1 = A 962 068 XX
- 2 = A 963 667 NU
- 3 = A 963 751 NU
- 4 = A 961 485 XX
- 5 = A 961 667 NU
- 7 = A 962 715 NU
- 8 = A 963 372 NU
- 9 = A 962 985 NU
- 11 = A 962 080 XX
- 12 = A 960 191 NU
- A 960 196 NU
- 14 = A 960 001 NU
- 15 = A 962 081 XX
- 16 = A 962 082 NU
- 17 = A 963 404 NU
- 18 = B 960 853 XX




**MELANGE**  
**A 4261.. A 5399 ..**


0811/ A 865 812 40  
 (+ A 865 612)  
 Made in Germany



**A5399..**








**A4261..**



Ideal Standard International BVBA  
 Chaussée de Wavre, 1789 - box 15  
 1160 Bruxelles  
 Belgium

www.idealstandardinternational.com





P	0.1 bar	Q	4.3 l/min	open top
P	3.0 bar	Q	5.0 l/min (Fitted outlet)	orange top

	<b>P</b>	<b>bar</b>	MIN. 0,1		<b>MAX.</b> 5
	<b>T</b>	<b>°C</b>	MAX. 80		65 40