




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, GN, ...

Pos.	Part No.
1	A 861 407 XX
2	A 861 412 NU
3	A 860 603 NU
5	A 861 446 NU
6	A 861 243 NU
8	B 961 383 XX
9	A 861 227 XX
10	A 860 607 NU
11	A 961 640 NU
14	A 961 689 NU
15	E 960 112 NU




Ideal Standard

CONNECT AIR


A 7031 ..



0919 / A 868384
 (+ A 865 612)
 Made in Germany



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





	P	bar			Q (3 bar)
	T	°C			l/min
					5